

HL Series

Hazardous Location Connection Kits (*cont'd.*)

Ordering Information



End Seal Kit for Hazardous Locations HL-ES 382221

- (1) 3/4" junction box
- (1) Seal fitting
- (1) End seal
- (1) Tube of RTV
- (1) Butt splice
- (1) Pipe stand-off
- (1) Sealing grommet
- (1) Sealing compound
- (1) Ring terminal
- (1) Green grounding wire



Splice Kit for Hazardous Locations HL-S 382205

- (1) 3/4" box
- (1) Cable entry fitting
- (2) 3/4" Seal fitting with nipple
- (1) Sealing compound & fiber
- (2) 4" 12 AWG leadwires (green)
- (1) Small RTV tube
- (2) Butt splice
- (2) Ring terminal
- (1) Pipe standoff
- (1) Sealing grommet
- (1) Stainless steel label
- (1) Conduit plug
- (1) Extra grounding screw
- (2) Wire nuts
- (2) Power termination seal
- (1) 3/4" to 1/2" reducing bushing




Power Connection Kit for Hazardous Locations HL-PC 382192

- (1) 3/4" junction box
- (1) Seal fitting
- (1) Ring terminal
- (1) Tube of RTV
- (2) Termination seal
- (1) Pipe stand-off
- (1) Sealing grommet
- (1) Conduit plug
- (1) Sealing compound
- (1) Butt splice
- (3) 12 AWG leads
- (4) Wire nuts



Tee Kit for Hazardous Locations HL-T 382213

- (1) 3/4" box
- (2) Cable entry fitting
- (3) 3/4" Seal fitting with nipple
- (2) Sealing compound & fiber
- (3) 4" 12 AWG leadwires (green)
- (1) Small RTV tube
- (3) Butt splice
- (3) Ring terminal
- (1) Pipe standoff
- (1) Sealing grommet
- (1) Stainless steel label
- (1) Extra grounding screw
- (2) Wire nuts
- (3) Power termination seal
- (2) 3/4" to 1/2" reducing bushing



Caution Labels CL-1 382424

- 5) Electric heat tracing caution labels; weather resistant



208 - 240V Division 1 Signal Light Kit D1SL2 393692

Explosion proof pilot light for use with HL-PC kit. Pilot light kit made with 3/4" NPSM threads and 8" flexible leads. Red LED lens. For 208-240V system.



120V Division 1 Signal Light Kit D1SL1 393684

Explosion proof pilot light for use with HL-PC kit. Can be used as a power connection light or end seal light. Pilot light kit made with 3/4" NPSM threads and 8" flexible leads. Red LED lens. For 120V system.

HL Series

Hazardous Location Connection Kits *(cont'd.)*



**Fiberglas® Tape
Cable Attachments**
FT-3 389941

66' Roll of glass cloth tape with pressure-sensitive thermosetting silicone adhesive 3/8" wide. 310°F (155°C) rating. Strap at one foot intervals at minimum application temperatures of -40°F (-40°C)



**Stainless Steel Pipe Strap Kit
Attachments**
PS-1, 3, 10 & 20

PS-1 (382352) 1/2 to 3/4" pipes
PS-3 (382360) 1 to 3-1/2" pipes
PS-10 (382379) 2-1/2 to 9" pipes
PS-20 (382256) 9" to 19.5" pipes



**Aluminum Tape
Cable Attachments**
AT-1 383355

180' Roll aluminum foil installation tape with pressure-sensitive acrylic adhesive. 2-mil thickness with high tensile strength; 2-1/2" wide. 200°F (93°C) rating. Minimum application temperatures 40°F (5°C)



Stripping Tool
393510

Tool for stripping the base jacket and the conductive matrix from the cable buss wires. The tool is stocked with 16 awg blades for stripping SRL, HSRL, SRM/E, HSRM and SRP and Thermwire products.